




Mining and Surface Certification International Certification Services (ICS)

CB_QMS_SD_59 / Rev 01 / 2017-06-14 / Page 1 of 1


IECEx Process (1): Technical





Mining and Surface Certification International Certification Services (ICS)

CB_QMS_SD_59 / Rev 01 / 2017-06-14 / Page 2 of 1



IECEx Process (2): Quality – QAR / FAR

QAR: Quality Assessment Report (Manufacture)
FAR: Facility Assessment Report (Repairs) **
** Accreditation application in process)

* Additional testing; assessments; reviews; surveillance and/or re-assessment audits may be additionally quoted

IECEX Process (3): Quality – Existing QAR

Note: MASC can either accept another IECEX CB's QAR for your project (in this case MASC will follow Process 3. If MASC is to take over your current QAR, please refer to Process 2.

* Additional testing; assessments; reviews; surveillance and/or re-assessment audits may be additionally quoted

